

SECRET

OUT54269

SECRET 192808Z

1964 OCT 19 20 58Z

25X1

1. CAMERA B 15 WAS USED IN MISSION 3954 FLOWN ON 16 OCTOBER 1964. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

20 OCT 1964

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY ATMOSPHERIC CONDITIONS.

B. 9R SIDE: EDGE FOG AND AN INTERMITTENT NARROW MINUS DENSITY STREAK IS PRESENT FROM HEAD TO TAIL ALONG THE INBOARD EDGE OF THE FILM. THE MINUS DENSITY STREAK RUNS ROUGHLY PARALLEL TO AND 0.070" FROM THE FILM EDGE. A FEW RANDOM PLUS DENSITY STREAKS, LOCATED ROUGHLY PARALLEL TO AND 1.30" FROM THE INBOARD EDGE, ARE ALSO DETECTABLE. AN EXCESSIVE NUMBER OF PINHOLES AND SMALL EMULSION LIFTS ARE NOTED THROUGHOUT FRAMES 1331-1463. MINOR ROLLER CHATTER TRACES ARE PRESENT ON THE OUTBOARD EDGE OF FRAMES 001-266. MANUFACTURER'S SPLICES WITH ASSOCIATED MINOR STATIC DISCHARGES ARE CONTAINED WITHIN THE FORMATS OF FRAMES 027 AND 1496. FRAMES 1230 AND 1935/1936 CONTAIN OPAQUE HEAT SPLICES.

C. 9L SIDE: EDGE STATIC IS PRESENT INTERMITTENTLY ALONG BOTH EDGES. A WANDERING RANDOM PLUS DENSITY STREAK IS OBSERVED ON NUMEROUS OCCASIONS. SLIGHT CRIMPING WAS NOTED ALONG THE OUT-

GROUP 1
Excluded from automatic
downgrading and
declassification

SECRET

-2-

BOARD EDGE ON FRAMES 2391 AND 2392. HEAT SPLICES OCCURRED WITHIN THE FORMAT OF FRAMES 0014 AND 1336. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 2160.

D. BOTH SIDES: THE TRACKING WAS SLIGHTLY TO ONE SIDE, CUTTING OFF THE CAMERA NUMBER ON THE 9L SIDE. THE FRAMES ARE TITLED 0001-2549 (COUNTER NUMBERS 0005-2553).

E. NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES WERE NOTED.

3. POSITIVE.

A. THE PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY ATMOSPHERIC CONDITIONS.

B. THE PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 40 PERCENT OF THE MISSION.

S E C R E T

-END OF MESSAGE-